

9754

1894

~~145-106.~~

279-99

See U.S. pat
(279-101)

Tool and Sockets

Fig. 1.

Fig. 2.






Fig. 3.



Threads of diff.
pitch cause
jamming between
tool shank B and
bolt E.

[This Drawing is a reproduction of the Original on a reduced scale]